FORM MR-AR (Revised 6/96)


STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	General Information
	1. Report Time Period: From (mo./yr.) 1-1-96 To (mo./yr.) 1-1-97
	2. DOGM File Number (Mine No): 5/025/02/ 950 5/037/093
	3. Mine Name: Moen Kopi Moca & Moen Kopi Hite
	4. Mineral(s) Mined (or permitted to mine): Sand 5 to N &
	5. Type of mine ☐ Surface Mine or ☐ Underground Mine
	6. Legal Description (Location of Lands Affected):
	NW 1/4, SE 1/4, Section 32 , Township $T435$, Range $R4W$
11-47138	ω_{14} , ω_{5} 1/4, Section 32, Township 345, Range 15 E
11-47138 L 47005	1/4,1/4, Section, Township, Range
	7. Name of Operator or Company: Brue H Hansen
	8. Permanent Street Address: 1345 So Stewart dv. Box341
	City, State, Zip: Kanah, Utah 84741 0341
	Phone: 801 3 644 3073
	9. Company Representative (or designated operator):
	Name: <u>Same as above</u>
	Title:
	Business Address:
	City, State, Zip:
	Phone:
	☐ Please check if any of the above information has changed since previous year.
II.	Mining and Reclamation
	1. Was the mine active during the past year? Yes □ No 🗓
	2. If active, how much ore or mineral was mined?

	3.	How much additional acreage was disturbed during the past year? None
	4.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
		Nonc
5.		How much acreage was reclaimed during the past year? None
6.		Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
7.		What is the total disturbed acreage at years end?
8.		Briefly summarize any mining and/or reclamation plans for the upcoming year. The Moen kopie Moca Quarry will be Opened in Tannery of 1997.
		January of 1997. The Moenkori Hite Guarry is on hold due to demand and finances
NOTE:		Section III., "Additional Information" applies only to large mining operations.
III. <u>Additi</u>	iona	al Information
1.		An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2.		Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV. Signat	ture	<u>Requirement</u>
Il	iere	by certify that the foregoing is true and correct.
		Name (Typed or Print): Bruce H Hansen
		Title of Operator:
		Signature of Operator: Bruce H Hausen
		Date: $\frac{2-20-97}{}$

jb MR-AR